

=> fil wpix

FILE 'WPIX' ENTERED AT 13:49:15 ON 18 JUL 2007
COPYRIGHT (C) 2007 THE THOMSON CORPORATION

FILE LAST UPDATED: 16 JUL 2007 <20070716/UP>
MOST RECENT THOMSON SCIENTIFIC UPDATE: 200745 <200745/DW>
DERWENT WORLD PATENTS INDEX SUBSCRIBER FILE, COVERS 1963 TO DATE

>>> IPC Reform backfile reclassification has been loaded to 31 May 2007. No update date (UP) has been created for the reclassified documents, but they can be identified by 20060101/UPIC and 20061231/UPIC and 20060601/UPIC. <<<

FOR A COPY OF THE DERWENT WORLD PATENTS INDEX STN USER GUIDE,
PLEASE VISIT:
http://www.stn-international.de/training_center/patents/stn_guide.pdf

FOR DETAILS OF THE PATENTS COVERED IN CURRENT UPDATES; SEE
<http://scientific.thomson.com/support/patents/coverage/latestupdates/>

>>> FOR DETAILS ON THE NEW AND ENHANCED DERWENT WORLD PATENTS INDEX
PLEASE SEE
http://www.stn-international.de/stndatabases/details/dwpi_r.html <<<

=> d his nofile

(FILE 'HOME' ENTERED AT 11:58:32 ON 18 JUL 2007)

FILE 'HCAPLUS' ENTERED AT 11:58:45 ON 18 JUL 2007

L1 1 SEA ABB=ON PLU=ON US2005112284/PN
SEL RN

FILE 'REGISTRY' ENTERED AT 11:59:17 ON 18 JUL 2007

L2 2 SEA ABB=ON PLU=ON (15522-12-0/BI OR 4196-86-5/BI)
D SCA

FILE 'WPIX' ENTERED AT 12:08:01 ON 18 JUL 2007

L3 1 SEA ABB=ON PLU=ON US20050112284/PN
D IFULL

FILE 'HCAPLUS' ENTERED AT 12:09:11 ON 18 JUL 2007

L4 304 SEA ABB=ON PLU=ON WICK? (3A) STRUCTURE
L5 QUE ABB=ON PLU=ON WICK?
L6 QUE ABB=ON PLU=ON FLUX
L7 QUE ABB=ON PLU=ON WELD? OR BRAZE# OR BRAZING
L8 QUE ABB=ON PLU=ON SOLDER# OR SOLDERED OR SOLDERING
L9 3352 SEA ABB=ON PLU=ON (L7 OR L8) (5A) REMOV?
L10 QUE ABB=ON PLU=ON DEWELD? OR DEBRAZ? OR DE (A) (WELD? OR
DEBRAZ?)
L11 QUE ABB=ON PLU=ON DESOLDER? OR DE (A) SOLDER?
L12 QUE ABB=ON PLU=ON METAL? (3A) (STRAND? OR STRING? OR
FILAMENT? OR THREAD?)
L13 QUE ABB=ON PLU=ON ROSIN? OR COLOPHON?
L14 QUE ABB=ON PLU=ON ESTER
L15 QUE ABB=ON PLU=ON ?CARBOXYLIC (2A) ACID
L16 11 SEA ABB=ON PLU=ON (L9 OR L10 OR L11) AND L5
L17 1043 SEA ABB=ON PLU=ON (L9 OR L10 OR L11) AND L6
L18 7 SEA ABB=ON PLU=ON L16 AND L17
L19 6 SEA ABB=ON PLU=ON L5 AND L12

L20 4 SEA ABB=ON PLU=ON L12 AND (L9 OR L10 OR L11)
 L21 1 SEA ABB=ON PLU=ON L12 AND L13 AND L14 AND L15
 L22 1213 SEA ABB=ON PLU=ON L6 AND L13
 L23 132 SEA ABB=ON PLU=ON L22 AND L14
 L24 22 SEA ABB=ON PLU=ON L23 AND L15
 L25 3 SEA ABB=ON PLU=ON L24 AND (L9 OR L10 OR L11)
 L26 18 SEA ABB=ON PLU=ON L24 AND (L7 OR L8)
 L27 18 SEA ABB=ON PLU=ON L25 OR L26
 L28 QUE ABB=ON PLU=ON MELTING(2A) (TEMPERATURE OR POINT)
 L29 0 SEA ABB=ON PLU=ON L27 AND L28
 L30 QUE ABB=ON PLU=ON (BENZO? OR AROMAT?) (2A)ACID
 L31 1 SEA ABB=ON PLU=ON L27 AND L30
 L32 18 SEA ABB=ON PLU=ON L31 OR L27
 L33 QUE ABB=ON PLU=ON HEAT(3A) CONDUCT?
 L34 13 SEA ABB=ON PLU=ON L16 OR L20
 L35 12 SEA ABB=ON PLU=ON L34 AND (L8 OR L11)
 L36 1 SEA ABB=ON PLU=ON L32 AND L35
 L37 29 SEA ABB=ON PLU=ON L32 OR L35
 L38 25 SEA ABB=ON PLU=ON L37 AND (1840-2003)/PRY,PY,AY

FILE 'WPIX' ENTERED AT 12:47:43 ON 18 JUL 2007

L39 46 SEA ABB=ON PLU=ON (L9 OR L10 OR L11) AND L5
 L40 18 SEA ABB=ON PLU=ON (L9 OR L10 OR L11) AND L12
 L41 6 SEA ABB=ON PLU=ON L39 AND L40
 L42 1 SEA ABB=ON PLU=ON (L39 OR L40) AND L33
 L43 887 SEA ABB=ON PLU=ON L6 AND L13
 L44 37 SEA ABB=ON PLU=ON L43 AND L28
 L45 130 SEA ABB=ON PLU=ON (L43 OR L44) AND L14
 L46 3 SEA ABB=ON PLU=ON L45 AND L30
 L47 26 SEA ABB=ON PLU=ON (L45 OR L46) AND L15
 L48 3 SEA ABB=ON PLU=ON L47 AND (L9 OR L10 OR L11)
 L49 20 SEA ABB=ON PLU=ON L47 AND (L7 OR L8)
 L50 20 SEA ABB=ON PLU=ON L48 OR L49
 L51 1 SEA ABB=ON PLU=ON (L39 OR L40) AND L50
 L52 25 SEA ABB=ON PLU=ON L41 OR L50
 L53 22 SEA ABB=ON PLU=ON L52 AND (1840-2003)/PY,PRY,AY

FILE 'WELDASEARCH' ENTERED AT 13:00:15 ON 18 JUL 2007

L54 17 SEA ABB=ON PLU=ON (L9 OR L10 OR L11) AND L5
 L55 2 SEA ABB=ON PLU=ON (L9 OR L10 OR L11) AND L12
 L56 1 SEA ABB=ON PLU=ON L54 AND L55
 D SCA
 L57 0 SEA ABB=ON PLU=ON (L54 OR L55) AND L33
 L58 372 SEA ABB=ON PLU=ON L6 AND L13
 L59 8 SEA ABB=ON PLU=ON L58 AND L28
 L60 7 SEA ABB=ON PLU=ON (L58 OR L59) AND L14
 L61 0 SEA ABB=ON PLU=ON L60 AND L30
 L62 0 SEA ABB=ON PLU=ON L60 AND L15
 L63 1 SEA ABB=ON PLU=ON L60 AND (L9 OR L10 OR L11)
 L64 7 SEA ABB=ON PLU=ON L60 AND (L7 OR L8)
 L65 7 SEA ABB=ON PLU=ON L63 OR L64
 L66 0 SEA ABB=ON PLU=ON (L54 OR L55) AND L65
 L67 25 SEA ABB=ON PLU=ON L54 OR L55 OR L65
 L68 25 SEA ABB=ON PLU=ON L67 AND (1840-2003)/PY,PRY,AY

FILE 'COMPENDEX' ENTERED AT 13:07:48 ON 18 JUL 2007

L69 11 SEA ABB=ON PLU=ON (L9 OR L10 OR L11) AND L5
 L70 0 SEA ABB=ON PLU=ON (L9 OR L10 OR L11) AND L12
 L71 0 SEA ABB=ON PLU=ON L69 AND L33
 L72 227 SEA ABB=ON PLU=ON L6 AND L13

L73 6 SEA ABB=ON PLU=ON L72 AND L28
 L74 0 SEA ABB=ON PLU=ON (L72 OR L73) AND L14
 L75 5 SEA ABB=ON PLU=ON (L72 OR L73) AND L15
 L76 5 SEA ABB=ON PLU=ON L75 AND ((L9 OR L10 OR L11) OR (L7
 OR L8))
 L77 0 SEA ABB=ON PLU=ON L69 AND L76
 L78 16 SEA ABB=ON PLU=ON L69 OR L76
 L79 15 SEA ABB=ON PLU=ON L78 AND (1840-2003)/PY,PRY,AY

FILE 'PASCAL' ENTERED AT 13:15:30 ON 18 JUL 2007

L80 3 SEA ABB=ON PLU=ON (L9 OR L10 OR L11) AND L5
 L81 0 SEA ABB=ON PLU=ON (L9 OR L10 OR L11) AND L12
 L82 58 SEA ABB=ON PLU=ON L6 AND L13
 L83 2 SEA ABB=ON PLU=ON L82 AND L28
 L84 1 SEA ABB=ON PLU=ON (L82 OR L83) AND L14
 L85 1 SEA ABB=ON PLU=ON (L82 OR L83) AND L15
 L86 1 SEA ABB=ON PLU=ON (L84 OR L85) AND ((L9 OR L10 OR L11)
 OR (L7 OR L8))
 L87 0 SEA ABB=ON PLU=ON L80 AND L86
 L88 4 SEA ABB=ON PLU=ON L86 OR L80

FILE 'WPIX' ENTERED AT 13:31:33 ON 18 JUL 2007

L89 QUE ABB=ON PLU=ON COMPONENT OR COMPRIS? OR COMPOSIT?
 OR FORMULAT? OR MIXTURE
 L90 19 SEA ABB=ON PLU=ON L50 AND L89
 L91 24 SEA ABB=ON PLU=ON L41 OR L90
 L92 21 SEA ABB=ON PLU=ON L91 AND (1840-2003)/PY,PRY,AY

FILE 'HCAPLUS' ENTERED AT 13:39:15 ON 18 JUL 2007

L93 12 SEA ABB=ON PLU=ON L27 AND L89
 L94 23 SEA ABB=ON PLU=ON L93 OR L35
 L95 19 SEA ABB=ON PLU=ON L94 AND (1840-2003)/PY,PRY,AY

FILE 'STNGUIDE' ENTERED AT 13:43:20 ON 18 JUL 2007

FILE 'WELDASEARCH' ENTERED AT 13:44:29 ON 18 JUL 2007

L96 2 SEA ABB=ON PLU=ON L54 AND L4
 L97 11 SEA ABB=ON PLU=ON L96 OR L55 OR L65
 L98 11 SEA ABB=ON PLU=ON L97 AND (1840-2003)/PY,PRY,AY

FILE 'WPIX' ENTERED AT 13:47:03 ON 18 JUL 2007

SEL L92 PN,APPS

FILE 'HCAPLUS' ENTERED AT 13:47:31 ON 18 JUL 2007

L99 22 SEA ABB=ON PLU=ON (W02001-US40518/APPS OR DE1983-332221
 L100 16 SEA ABB=ON PLU=ON L95 NOT L99

FILE 'HCAPLUS, WELDASEARCH, PASCAL' ENTERED AT 13:48:24 ON 18 JUL
 2007

L101 28 DUP REM L100 L98 L88 (3 DUPLICATES REMOVED)

=> d l92 ifull 1-21

L92 ANSWER 1 OF 21 WPIX COPYRIGHT 2007 THE THOMSON CORP on STN
 ACCESSION NUMBER: 2006-443703 [45] WPIX
 CROSS REFERENCE: 2004-080332
 DOC. NO. CPI: C2006-138747 [45]